



FIG_34: Stress History and Vane Shear Strengths Muni Metro Turnback Site