



FIG\_36A: Undrained Shear Strengths from Vane Shear Tests Davidson Street: South of Islais Creek Channel