



**Picture 1:**  
Typical core of Mélangé Matrix, as recovered in the field.



**Picture 2:**  
Close-up view of core recovered from borehole LB-03.



**Picture 3:**  
View of core cross-section illustrating irregular contacts between different materials, and laminated structure.



**Picture 4:**  
Close-up view illustrating contorted and laminated structure.



**Picture 5:**  
Close-up view illustrating evidence of shear deformations and slickensides.



**Picture 6:**  
Close-up view that shows the presence of slickensides.