



FIG_242: Lateral Deflections Versus Excavation Depth: Overflow Structure Along Islais Creek