



FIG_245: Islais Creek Contract E Lateral Deformations Caused by Jet Grouting and Excavation

W:\Infrastructure\Geotech\UC Berkeley 2008 Seminar\Final Figures\11 EXCAVATION\FIG_239.ai