



Clough and Reed (1984)

FIG_246: Subsurface Conditions and Soil Properties: Davidson Street Sewer (Clough and Reed, 1984)