



Plate L-02: Stress History and Undrained Shear Strength Profiles for Bay Bud: Condition Under Downstream Slope of the Pacheco Pond Levee