



FIG_F-01: Figure A: Typical Measured Lateral Movements for Deepening Excavation on Davidson Avenue-Inclinometer No. 7
 Figure B: Maximum Measured Lateral Movements in All Inclinometers Except Nos. 3 and 4